	3 11039	CONTRACTOR OF THE							L. T. PES	
	et a par	edeptions				HESSAME			1990	TENNESS OF THE PROPERTY OF THE
	district.	#205Z 23 00	ed For Rei	ease 2002/			112	0020042-1	O Company of the control of the cont	energy (* 1840)
5X1A 5X1A				lite apper, and	सः (दाष्ट्रामः) गाः । सा स्थानक्रिकः	Tradestry organic destructions	4		2	THE STATE OF STATES
	her describing		regage (200 ° se monte, e gale) e novembre e novembre esta e		200 - 14 (2012年 1973年	And the second property of the second beauty	2 = 51		131	では、100円である。 100回でも 100回で
	The state of	DIRECTOR					7		16 15	er main ance
	SOM I				10				16	OROSON BRADES.
				,	166			Market Bank in the Architecture of the speed of the 1986	的情况的现在分词的" 有题的特殊"则 是不是"是"。	Telebraican Madematria
	AGTI ON s			ak é	35%		PERTURATE TO STATE OF THE PERTURATION OF THE PERTUR	IMMEDI	ATE	
	125 () 1			1/					CARREST OF THE THIRD PROPERTY.	
								2001 2001 8501		
•				~						
5X1A	The growth branch to those or	TOR Ø221Z 2	3 OCT 6	55	Silata - Prinsipalania aliminia dalife diagrama Tangga di Prinsipalania (S. Mariana) an	O section of the sect	PS 1-10		IN 67	010
	253			(PM)				CHE		
		RYBAT							2	5X1A

FROM SHELTON

2

- 1. AS OF SATURDAY MORNING 0130Z NOTHING NEW TO REPORT.

 RESCUE OPERATIONS UNDERWAY COVERING ENTIRE AREA, INCLUDING

 TWO H-19°S WORKING OVER LAND. ONE US DESTROYER ARRIVED AND

 JOINED SEARCH OPERATIONS AT DAYLIGHT.
- 2. DURING 1962 I WAS INVOLVED WITH AIRCRAFT ACCIDENT INVESTIGATION ON LAKE SUPERIOR LOOKING FOR SUBMERGED WRECKAGE.

 US NAVY UNDERWATER TELEVISION COVERAGE WAS UNSUCCESSFULLY

 USED DUE TO SHIFTING SILT AND SAND. BELIEVE WE MAY BE ABLE

 TO GENERALLY LOCATE ARTICLE 352 AND USE SOME OF THE LATEST

 NAVY UNDER WATER EQUIPMENT. REQUEST YOU DETERMINE AND ADVISE

 WHAT NAVY CAPABILITY AND EQUIPMENT WE COULD EXPECT. I'LL

 TRY TO DETERMINE TODAY WHAT THE AVERAGE WATER DEPTHS ARE AND

 ADVISE.
- 3. GOING NOW TO THE JOC.

END OF MESSAGE

T O P S E C R E T

